Woodruff Block (Rizzuto Building) 22-24 West First Street La Junta Otero County Colorado HABS No. CO-75

HABS COLO, 45-LAJUN, 1-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Rocky Mountain Regional Office
Department of the Interior
P.O. Box 25287
Denver, Colorado 80225

Form 10-920 (June 1983)

UNITEO STATES OF PARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS COLO, 45-LAJUN,

ARCHITECTURAL DATA FORM

STATE	COUNTY	COUNTY Otero		TOWN OR VICINITY La Junta	
Colorado	Otero				
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)				HABS NO.	
Woodruff Block			÷	CO-75	
SECONOARY OR COMMON NAMES	OF STRUCTURE				
Rizzuto Building					
COMPLETE ADORESS (DESCRIBE L	OCATION FOR RURAL	SITES)	· · · · · · · · · · · · · · · · · · ·		
22-24 West First Str	eet; southeast co	rner of First and	d Santa Fe	Avenue	
OATE OF CONSTRUCTION (INCLUE	ARCHITECT(S) (INCLUDE SOURCE)				
January to August, 1892		W. H. Robinson			
SIGNIFICANCE (ARCHITECTURAL)	AND HISTORICAL, INC.	l LUDE ORIGINAL USE (OF STRUCTUR	?E)	
One of the first bui	ldings in downtow	n La Junta to be	built of m	aterial other than	
and a drugstore call	ed Joy & Company.		raile of h.	C. Draper & Company	
STYLE (IF APPROPRIATE) Rich	ardsonian Romanes	ane			
MATERIAL OF CONSTRUCTION (IN			· 		
Native limestone					
SHAPE AND DIMENSIONS OF STRUE 50' x 140': front 80				RE ACCEPTABLE)	
EXTERIOR FEATURES OF NOTE			· · · · · · · · · · · · · · · · · · ·	3	
Random ashlar limesto	one with plain ho	rizontal window a	ınd door li		
INTERIOR FEATURES OF MOTE (D)	CODING FLOOR RIANG	LE NOT CHETOUED	· · · · · · · · · · · · · · · · · · ·		
INTERIOR FEATURES OF NOTE (DE					
Downstairs consists of Street and four small	Di six separate co Ler ones facino Se	ommercial areas;	two large		
down the center and	four rooms on each	side.	ine upstai	rs has a hallway	
MAJOR ALTERATIONS AND ADOIT	IONS WITH OATES				
No major alterations by rearrangint the wa	were made to the alls; one-story pa	structure. Inte art of structure	rior arran was stucco	gement was changed on the street side.	
PRESENT CONDITION AND USE					
Extremely deteriorate	ed; currently vaca	int.			
OTHER INFORMATION AS APPROP	RIATE			<u> </u>	
		•			
SOURCES OF INFORMATION (INCL.		TIONAL REGISTER, S	TATE REGISTI	ERS, ETC.)	
Frances Keck, local h		_			
Structure was determi	ned eligible for	listing on the N	ational Reg	gister.	
COMPILER, AFFILIATION Dan Noller, Administr	ative Assistant,	City of La Junta		OATE 7/18/85	
		<u> </u>		<u> </u>	